

file: \NOAA\Resonon\2019-05_re-assembly\Resonon_re-assembly_notes.xlsx

date: 02-May-2019; by: MF; (rev: 03May2019)

what: Shipping specs & cameras to Resonon for re-assembly after wedge-window repairs

FedEx piece#	Resonon Spec.	Assy. with "CCD-"	Mark's FedEx *.pdf	FedEx Tracking #	Where at now	Notes
1	BS01	17878	Spec01	7751 1727 9440	rm124, shelf	check r.e. variable track location
2	BS02	16345	Spec02	7751 1732 0278	rm124, shelf	
-	BS03	16346	na	na	in MOBY267	
3	BS04	17881	Spec03	7751 1733 1893	fume hood	
4	BS05	20477	Spec04	7751 1734 5720	box	
5	BS06	22932	Spec05	7751 1735 4037	box	
6	RS01	17898	Spec06	7751 1736 3498	box	
7	RS02	17880	Spec07	7751 1737 1290	rm124, shelf	
-	RS03	19348	na	na	in Miami	
-	RS04	19347	na	na	in MOBY267	
8	RS05	16343	Spec08	7751 1738 0159	box	
9	RS06	16344	Spec09	7751 1738 9903	box	
FedEx piece#	Andor Camera "CCD-"	Assy. with Spec.	Mark's FedEx .pdf	FedEx Tracking #	Andor repair RMA #	Where / Notes
10	17878	BS01	CCD01	7751 1742 5342	R62042	
11	16345	BS02	CCD02	7751 1743 9463	na	Andor repair Jul-2017
-	16346	BS03	na	na	na	in MOBY267
12	17881	BS04	CCD03	7751 1744 9372	R62045	
13	20477	BS05	CCD04	7751 1745 6970	R62047	
14	22932	BS06	CCD05	7751 1746 4567	R62046	CCD-22932 replaces CCD-20476
15	17898	RS01	CCD06	7751 1747 2094	R62042	
16	17880	RS02	CCD07	7751 1748 0037	R62044	
-	19348	RS03	na	na	na	in Miami
-	19347	RS04	na	na	na	in MOBY267
17	16343	RS05	CCD08	7751 1748 6881	R62040	
18	16344	RS06	CCD09	7751 1749 6746	R62041	